



Y = Spring-Loaded

0 = Not Required

Spring-Loaded Probe BOX 10

Special Requirements BOX 11

X = Specify

0 = None

Fractional inches

0 = 0"

1 = 1/8"

 $\frac{2}{1} = 1/4$ "

3 = 3/8"

4 = 1/2"

5 = 5/8"

6 = 3/4"

7 = 7/8"

onnection Head(Temperature Sensor Enclosure)



Mini Head 1



Mini Head 2



Mini Head 3



Plastic Head



Small Bakelite Head











Weather Proof Head Weather Proof Head(BIG) Hinge Type Head

Imported Head 1

Imported Head 2



Imported Head 3



Imported Head 4



Flame Proof Head 1



Flame Proof Head 2 (II C APPROVED)



IP-65 HEAD



SS Head



SS Head (SMALL)



Stainless Steel(SS) Head 1



Stainless Steel(SS) KNE Type Head Head 2



Contact: +91-22-26773837 Telefax: +91-22-66954779 Mobile: +91-9967642914